

June 19, 1980

1-X)
2
178
m

SUBJECT: Unsafe Area

TO: Mr. Wolfgang, Safety Officer

FROM: *P.D. Donato*
Patricia Donato, OTR

The walls of the tunnel connecting Washington Unit and Buchanan Hall have large flaking areas. With the increased traffic between buildings, this condition has NOT improved.

Blind clients should be able to run their hands along the wall for independent travel but this is not possible because of the flaking. Also they risk getting paint chips under their fingernails.

Although I have been told this is lead free paint, it is hard to believe that all layers are lead free. Many clients pick up pieces and some try to eat these chips.

cc: David Pool
Vivian Hilker
O.T. File

MAINTENANCE WORK ORDER (MWO)

			MWO NUMBER	DATE
				9/5/80
BUILDING	ROOM NO.	WRITER	BLDG. APPROVAL	TELEPHONE NUMBER
Buchanan	Ky Hall	<i>SE</i> E. Edwards	<i>V.H.</i> V. Hilker	553
JOB DESCRIPTION				DATE REQUIRED
Request installation of hand rail from bus shelter at Buchanan				9/19/80
Keystone Hall into Buchanan Hall. This should be on Right side of sidewalk				
going into building so as not to obstruct crosswalk.				
Needed as guide for blind and assist for physically handicapped.				
Thank you.				
(Do not write below line)				
TRADE ASSIGNED	MEN ASSIGNED		CODE NO	
TOTAL TIME - HRS.	PM NO.		HISTORY ENTRY	
Completion Approval By			Forman's Approval	Authorized By
				<i>[Signature]</i>

Record Material and Cost on Reverse
Commonwealth of Pennsylvania

FORWARD TO MAINTENANCE OFFICE
Department of Public Welfare

PW 257 - 2-77